



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 04/29/2015

Reviewed

[Signature]

Mine Name: Silliman Rock Quarry	Permit Number: S/015/0103	Mine Status: Proposed
Operator Name: Michael and Sandra Silliman	Inspection Date: 04/21/2015	Permit Fees:
Inspector(s): Wayne Western	Inspection Time: 11:30 - 12:20	Bond Amount:
Attendee(s): Michael and Sandra Silliman	Weather: mild and sunny	Bond Escalation:
Inspection Purpose: Operator request		Prior Inspection:

Conclusions and Recommendations

The purpose of this inspection was to meet with the Operator on site and determine what areas should be bonded. The Operator had originally request that a permitted area of nearly 9 acres. In order to reduce the bond the Division suggested that the site be reduced in size. Also the Operator should put in for a variance to leave the road after reclamation for access.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The Operator has concerns about getting the slopes back to 45 degrees. The Operator may apply for a varinace. Reason for the variance could include limited height and stable rock face.			
3.	Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M015-Emery/E0150095SillimanRockQuarry/Inspection/Insp-04212015aaa.pdf



Area that had been previously mined. The Operator has concerns about getting the slope to 45 degrees.



Existing highwalls with pit in the right corner



Area where Operator intends to mine. Plan is to get rocks larger than four feet for rip rap.



Proposed pit and access road.